

155703

Wednesday, January 18, 2017 7:27:40 AM

N900040100

Setup Start *NS1*

Stop *NS2*

Start Date: 1/11/2017 **Start Qty:** 1.00

Cust Item ID:

Required Date: 1/17/2017 **Req'd Qty:** 1.00

Customer:

Reference:

Approvals: **Process Plan:** MF

Date: 17-1-20

Tooling:

Date:

Run Start *NR1*

QC: _____

Date: _____

SPC (Y/N):

Date:

Stop *NR2*

[illegible]

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition			Completed By
					Lead hand / Supervisor Approval Verification
					QC / QA Coordinator Approval
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER : _____					

155703

Wednesday, January 18, 2017 7:27:40 AM

N900040100

Setup Start *NS1*

Stop *NS2*

Start Date: 1/11/2017 **Start Qty:** 1.00 ***1***

Cust Item ID:

Required Date: 1/17/2017 **Req'd Qty:** 1.00 *** 1 ***

Customer:

Reference:

Approvals: **Process Plan:** _____ **Date:** _____ **Tooling:** _____ **Date:** _____

Run Start *NR1*

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop *NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

130

0,00

130

Packaging

0.00

Packaging

Memo

Identify and pack for shipping as per PPP D412-705-015
Location FG027

Packaging

4

DAS
28
9-80

DAS
27
9-89

FEB 22 1947

140

QC21- Final Inspection - Work Order Release

0.00

140

Memo

0.02

QC

Quality Control

DAS
21
9-89

~~FEB 23 2017~~

DAS
21
9-89

FEB 23 2017

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐	OTHER : _____			

Picklist Print

Tuesday, January 17, 2017 1:14:48 PM

Page 1

Work Order ID: 155703

155703

Parent Item: D412-705-015

D412-705-015

Parent Item Name: Drive Shaft Tunnel Modification

Start Date: 1/11/2017

Required Date: 1/17/2017

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP Rev:B Removed Manufacturing 06-10-03 JLM
IPP Rev:C ECN 1052 07-11-05 DD verified by:EC IPP Rev:D
ECN 12-670 12.11.07 DD Verified by:JLM IPP REV:E 16.10.05
NOW @ CHG006 DD VERF:JFS

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
AN3C3A		Purchased	No			110	Each	331.0000	22	22	88		

AN3C3A
Bolt

**

Location

Loc Qty

Loc Code

GA	65	
m134055	65	
OVER002	100	
m136182	100	
ST350	166	
m135898	166	

DAS
28
9-89

136740 * 18

70

DAS
6
9-89

DAS
27
FEB 09 2017-89

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
2401 85 28-6				2401 85 28-6					
								Completed By	

Root Cause				FAULT CATEGORY			
Environment	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐
Design	☐	Operator	☐	Bending	☐	Set-up	☐
Doc/Data	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐
Equip/Tooling	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐
Handling/Pre	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐
Material	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐
Internal Transport	☐	Poor Information	☐	Crushing	☐	Countersink	☐
Tribal Knowledge	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐
LOA	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐
Substation	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐
Past Expiry Date	☐	Manufacturing Process	☐	OTHER : _____			
Misidentified	☐	Past Due	☐				

Picklist Print

Page 2

Tuesday, January 17, 2017 1:14:48 PM

Work Order ID: 155703

155703

Parent Item: D412-705-015

D412-705-015

Parent Item Name: Drive Shaft Tunnel Modification

Start Date: 1/11/2017

Required Date: 1/17/2017

Start Qty: 1.00

Required Qty: 1.00

AN3C4A

Purchased

No

110

Each

1,552.000

3

3/2

AN3C4A

Bolt

**

DAS
6
9-89

FEB 09 2017

DAS
27
9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

FG	20
122814	20
FP001	848
M133440	7
M134396	41
M134509	6
M134606	29
M134676	44
M134762	106
M134861	13
M135058	123
M135127	22
M135297	52
M135442	2
M135774	53
M135864	64
M135948	17
M136295	28
M136579	241
OVER002	500
M136450	500
ST350	184
M135704	184

D3256-1

Manufactured

No

110

Each

4.0000

1

12
124

D3256-1

Access Panel

**

DAS
6
9-89

FEB 09 2017

DAS
27
9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

ST486	4
152822	4

Tuesday, January 17, 2017 1:14:49 PM

Shop Packet Print

Page 2

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER : _____					

Picklist Print

Page 3

Tuesday, January 17, 2017 1:14:49 PM

Work Order ID: 155703

155703

Parent Item: D412-705-015

D412-705-015

Parent Item Name: Drive Shaft Tunnel Modification

Start Date: 1/11/2017

Required Date: 1/17/2017

Start Qty: 1.00

Required Qty: 1.00

D3256-3 Manufactured No

110 Each

6.0000

D3256-3

Gasket

DAS
28
9-89

**

LocationLoc QtyLoc Code

ST486

6

152426

6

110 Each

768.0000

MS20427M3-3

Purchased

No

MS20427M3-3

Rivet

DAS
28
9-89

**

LocationLoc QtyLoc Code

GA

713

m134738

713

ST311

55

m133577

55

110 Each

189.0000

MS21060-L3K

Purchased

No

MS21060-L3K

Nut Plate

DAS
28
9-89

**

LocationLoc QtyLoc Code

GA

27

m135297

27

ST300

162

m135948

87

m136047

25

m136182

25

m136579

25

110 Each

297.0000

MS9321-09

Purchased

No

MS9321-09

Washer

DAS
28
9-89

**

LocationLoc QtyLoc Code

ST267

297

m135544

297

Tuesday, January 17, 2017 1:14:49 PM

Shop Packet Print

Page 3

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐	OTHER : _____			

Work Order ID 155703

Thursday, February 09, 2017 9:27:19 AM

155703

Page 1

Item ID: D412-705-015

Accept

N900040100

Setup Start

NS1

Revision ID:

Stop

NS2

Item Name: Drive Shaft Tunnel Modification

Start Date: 1/11/2017 Start Qty: 4.00

4

Cust Item ID:

Required Date: 1/17/2017 Req'd Qty: 4.00

4

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start

NR1

QC:

Date:

SPC (Y/N):

Date:

Stop

NR2Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

Draw Nbr

Revision Nbr

IIN-D412-750-1

A

DAS
21
9-89

FEB 09 2017

100

Document Control

0.00

100

DC

Memo

0.00

Doc.Control -USB or Paperwork

Photocopy bluefile & type labels per PPP D412-705-015 CHG 006

110

Pick Kit

0.00

110

Packaging

Memo

0.00

Packaging

120

QC4- 100% Inspect kits for completeness

0.00

120

QC

Memo

0.02

Quality Control

REFERENCE ONLY

5.0 PARTS LIST

Qty -011	Qty -013	Qty -015	Qty -017	Qty -019	Qty -021	Qty -023	Part Number	Description
X							D412-705-011	TWIN PAK E-Z ACCESS KIT
1	X						D412-705-013	INTAKE PLENUM ACCESS PANEL KIT
1		X					D412-705-015	DRIVESHAFT TUNNEL MODIFICATION KIT
1			X				D412-705-017	N1 GEARBOX ACCESS PANEL KIT
1				X			D412-705-019	C-BOX OIL COOLER LINE SUPPORT ACCESS KIT
1					X		D412-705-021	OIL PRESSURE TRANSMITTER ACCESS KIT
1						X	D412-705-023	OIL COOLER SUPPORT REMOVABLE LOWER PANEL KIT
	1						D3245-041	ACCESS PANEL ASSEMBLY, LH
	1						D3245-042	ACCESS PANEL ASSEMBLY, RH
	2						D3245-043	DOOR ASSEMBLY
	2						D3245-9	GASKET
	2						D3245-11	GASKET
	2						D3245-13	GASKET
			1				D3255-041	ACCESS PANEL ASSEMBLY, LH
			1				D3255-042	ACCESS PANEL ASSEMBLY, RH
		1					D3256-1	ACCESS PANEL
		1					D3256-3	GASKET
				1			D3259-041	ACCESS PANEL ASSEMBLY, LH
				1			D3259-042	ACCESS PANEL ASSEMBLY, RH
					1		D3307-041	ACCESS PANEL ASSEMBLY
						30	AN3-3A	BOLT
		22	30		6		AN3C3A	BOLT
		3					AN3C4A	BOLT
						30	AN960JD10	WASHER
16		44	36		12		MS20427M3-3	* RIVET
						4	MS21051-L3K	NUT PLATE
8		22	18		6		MS21060-L3K	NUT PLATE
						18	MS21069-L3K	NUT PLATE
		25	30		6		MS9321-09	WASHER

* Acceptable to substitute for MS20615M3-3 rivets. At installation, it is acceptable to use longer rivets if required.